

Whidden Gunworks

Pointing Die

Insert Chart

			Correct Die Insert
.224 caliber			
Berger	70	VLD	0
Berger	73	BT	2
Berger	75	VLD	1
Berger	77	BT	2
Berger	80	VLD	1
Berger	82	BT Target	0
Berger	90	VLD	1
Berger	90	BT Target	1
Sierra	52	MK	2
Sierra	69	MK	2
Sierra	77	MK	2
Sierra	80	MK	0
Nosler	77	CC	2
Nosler	52	CC	2
Hornady	68	BTHP	0
Lapua	69	Scenar	2
.243 caliber			
Berger	90	BT	0
Berger	95	VLD	1
Berger	105	VLD	1
Berger	105	BT	0
Berger	108	BT	0

Whidden Gunworks

Pointing Die

Insert Chart

Berger	115	VLD	1
Sierra	70	MK	2
Sierra	95	MK	0
Sierra	107	MK	0
Hornady	87	HPBT	2
Lapua	90	Scenar	0
Lapua	105	Scenar	1
DTAC	115	HPBT	0
.264 caliber			
Berger	100	BT	0
Berger	120	BT	0
Berger	130	VLD	1
Berger	140	VLD	1
Berger	140	LRBT	1
Berger	140	BT	0
Sierra	107	MK	0
Sierra	123	MK	0
Sierra	142	MK	0
Nosler	140	CC	2
Lapua	108	Scenar	0
Lapua	139	Scenar	0
.277 caliber			
Berger	130	VLD	0

Whidden Gunworks

Pointing Die

Insert Chart

Berger	140	VLD	0
Berger	150	VLD	0
Sierra	115	MK	Won't point well.
Sierra	135	MK	0
.284 caliber			
Berger	168	VLD	1
Berger	180	VLD	1
Berger	180	BT	0
Sierra	168	MK	0
Sierra	175	MK	0
JLK	180	HPBT	1
.308 caliber			
Berger	155	BT	2
Berger	155	VLD	1
Berger	155.5	BT	0
Berger	168	BT	0
Berger	168	VLD	1
Berger	175	VLD	1
Berger	175	BT	0
Berger	185	VLD	1
Berger	185	BT	0
Berger	190	VLD	1
Berger	210	VLD	1
Berger	210	BT	0

Whidden Gunworks

Pointing Die

Insert Chart

Sierra	155	MK (2155)	2
Sierra	168	MK	2
Sierra	175	MK	2
Sierra	180	MK	2
Sierra	190	MK	2
Sierra	200	MK	2
Sierra	220	MK	2
Sierra	220	MK	2
Sierra	240	MK	2
Nosler	168	CC	2
Hornady	168	HPBT	0
Lapua	155	Scenar	0
Lapua	167	Scenar	2
HBC	155	Australian	1